

Technical drawings of a PCB assembly. The top left shows a side view of a horizontal PCB with a central rectangular cutout. The top right shows a cross-section view of the PCB with dimensions 33 and 3. The bottom left shows a top-down view of the PCB with dimensions 508, 266, 612, and 304. The bottom right shows a 3D perspective view of the PCB assembly with four screws labeled 9905, 34962, 33763, and 35415.

